File: Mo1-0036 m0470036 cc Paul



## TEMPLE MOUNTAIN ENERGY, INC.

"Providing Enhanced Oil Recovery Technologies"

4526 Ridgeview Dr. Eagan, MN 55123 Phone (651) 452-7125 Fax (651) 905-1998 12<sup>th</sup> December 2006

Department of Natural Resources Division of Oil, Gas & Mining. 1594 West, North Temple. Suite 1210, PO Box 145801 Salt Lake City Utah 84114-5801

For the Attention of; - Paul B. Baker.

In respect of; - Cessation Order No. MC2006-03-14-01

Dear Sirs.

Further to the above mentioned notice and our subsequent discussions with you we hereby attach our drawings and associated GPS logs for the small mine permit area as requested.

In addition to the supply of the requested information we would like to reiterate that due to the proximity of previous operations, abandoned materials and equipment, along with the impact from previous operators exploratory works as well as public access issues it was never the intention of TME Inc or TME AR LLC to encroach beyond the permitted 5 acre small mine area.

It is our intention however to be responsible for all our operational areas nationally or internationally as we are committed to ensuring minimal impact on the environment. TME has endeavored to remove and tidy the adjacent impacts and abandonment's in close proximity to our operation, to reduce overall residual risk and to improve the visual amenity of our works. Along with this we have had to manage public ingress and access through the mine site for others using the pre-existent and pre- installed roadways.

As demonstrated TME had instigated a reclamation plan to include some of these areas and that created by our own establishment operations, and as discussed we will complete the sub-soil works prior to the Christmas Holiday period and electronically transmit the photographs of such prior to topsoil replacement. The topsoil operation and seeding will be completed concurrently to ensure loose placement as instructed, this will commence as the weather conditions permit.

As reviewed at our meeting on site the heath, safety and environmental violations concerned us greatly and we would like to assure you and your colleagues the TME board will does not take these issues lightly and will ensure all future compliances as a matter of course.

Jim Runquist CEO Temple Mountain Energy Inc. RECEIVED

DEC 1 4 2006




RECEIVED

DEC 1 4 2006

TME Mine mapping Co-ordinates. GPS 11th Dec 2006

the second secon			and the second second second
Waypoint	33	N40 20.120 W109 29.476	5050 ft
Waypoint	34	N40 20.114 W109 29.465	5052 ft
Waypoint	35	N40 20.121 W109 29.447	5046 ft
Waypoint	36	N40 20.123 W109 29.437	5046 ft
Waypoint	37	N40 20.114 W109 29.393	5033 ft
Waypoint	38	N40 20.122 W109 29.383	5041 ft
Waypoint	39	N40 20.136 W109 29.381	5049 ft
Waypoint	40	N40 20.145 W109 29.389	5044 ft
Waypoint	41	N40 20.167 W109 29.408	5036 ft
Waypoint	42	N40 20.186 W109 29.441	5044 ft
Waypoint	43	N40 20.197 W109 29.448	5058 ft
Waypoint	44	N40 20.200 W109 29.449	5057 ft
Waypoint	45	N40 20.191 W109 29.472	5053 ft
Waypoint	46	N40 20.193 W109 29.490	5049 ft
Waypoint	47	N40 20.199 W109 29.510	5042 ft
Waypoint	48	N40 20.182 W109 29.497	5052 ft
Waypoint	49	N40 20.178 W109 29.491	5051 ft
Waypoint	50	N40 20.155 W109 29.529	5034 ft
Waypoint	51	N40 20.132 W109 29.515	5038 ft

RECEIVED DEC 1 4 2006



TME Asphalt Ridge LLC. 5 Acre Small Mine.

DEC 1 4 2006